

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2010 Levee Inspection Results**

**Reclamation District No. 0785 Driver**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Reclamation District No. 0785 Driver**

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	2.31

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/12/2010 - 5/12/2010			
DWR Inspector	John Williamson			
Accompanied By	Jim Eckman			
	Bill Mattos RD 785			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0785 Driver**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Sacramento River						Right	2.31	05/12/2010 05/12/2010	John Williamson	

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.29	0.29	Earthen Levee	Vegetation	LS	W	Elderberries are blocking visibility and flood fight capability.	38.658467 ° -121.609573 °	38.658467 ° -121.609573 °	1 Y
2	0.41	0.45	Earthen Levee	Vegetation	LS	W	Elderberries are blocking visibility and flood fight capability.	38.657168 ° -121.608270 °	38.656697 ° -121.607845 °	2 Y
3	0.59	0.59	Earthen Levee	Encroachments	LS	PO	Buildings	38.655097 ° -121.606590 °	38.655097 ° -121.606590 °	3
4	0.85	0.94	Earthen Levee	Vegetation	LS	W	Elderberries are blocking visibility and flood fight capability.	38.651863 ° -121.604158 °	38.650777 ° -121.603182 °	5
5	1.32	1.32	Earthen Levee	Vegetation	LS	W	Elderberries are blocking visibility and flood fight capability.	38.646712 ° -121.599095 °	38.646712 ° -121.599095 °	6
6	1.65	1.65	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level. Inspector Comments: this is the Haskin Ranch slope has some landscape and stairs on it	38.643310 ° -121.595138 °	38.643310 ° -121.595138 °	4
7	2.04	2.14	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: pine trees need to be raised for 5' clearance	38.641623 ° -121.588558 °	38.642005 ° -121.586993 °	8 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0785 Driver**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	2.31	05/12/2010 05/12/2010	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.29
End Levee Mile	0.29
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Elderberry

johnwgw\_s\_20100608\_250.jpg



Levee Mile Report Line	2
Start Levee Mile	0.41
End Levee Mile	0.45
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Elderberry

johnwgw\_s\_20100608\_251.jpg



Levee Mile Report Line	7
Start Levee Mile	2.04
End Levee Mile	2.14
Location	Land Side
Category	Earthen Levee
Item	Encroachments

pines and oleanders along shoulder

johnwgw\_s\_20100608\_252.jpg

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Reclamation District No. 0785 Driver**

Waterway			Bank	Unit Miles
Unit No. 02 Yolo Bypass			Left	3.30
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/13/2010 - 5/13/2010			
DWR Inspector	John Williamson			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0785 Driver**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 Yolo Bypass						Left	3.30	05/13/2010 05/13/2010	John Williamson	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.03	0.03	Earthen Levee	Encroachments	WS	C	Debris	38.640600 ° -121.620222 °	38.640600 ° -121.620222 °	7
2	0.61	0.61	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.632821 ° -121.615365 °	38.632821 ° -121.615365 °	1 Y
3	0.61	0.61	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.632821 ° -121.615365 °	38.632821 ° -121.615365 °	2 Y
4	0.66	3.25	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	38.632402 ° -121.615109 °	38.600047 ° -121.590769 °	3
5	0.66	0.82	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	38.632350 ° -121.615280 °	38.630133 ° -121.613985 °	9
6	0.66	0.94	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.632348 ° -121.615282 °	38.627797 ° -121.613642 °	8
7	0.83	0.83	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.630157 ° -121.613842 °	38.630157 ° -121.613842 °	10
8	0.98	0.98	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.628215 ° -121.613448 °	38.628215 ° -121.613448 °	11
9	1.50	1.50	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.621603 ° -121.607648 °	38.621603 ° -121.607648 °	12
10	1.53	1.89	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.621372 ° -121.607354 °	38.616802 ° -121.603838 °	4
11	1.53	1.89	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.621372 ° -121.607354 °	38.616802 ° -121.603838 °	5
12	1.67	1.67	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.619492 ° -121.606132 °	38.619492 ° -121.606132 °	13
13	3.20	3.20	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.600422 ° -121.591438 °	38.600422 ° -121.591438 °	14

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0785 Driver**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	3.30	05/13/2010 05/13/2010	John Williamson

Levee Mile Report Line	2
Start Levee Mile	0.61
End Levee Mile	0.61
Location	Water Side
Category	Earthen Levee
Item	Vegetation

thistle at gate waterside

johngw\_s\_20100518\_179.jpg



Levee Mile Report Line	3
Start Levee Mile	0.61
End Levee Mile	0.61
Location	Land Side
Category	Earthen Levee
Item	Vegetation

thistle at gate

johngw\_s\_20100518\_178.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected